


LEGEND

- SOIL BORING
- LOWER UNIT MONITORING WELL
- MONITORING WELL NOT SCREENED IN THE LOWER UNIT

ND NO DETECTION OF VOCs
NS NO SAMPLE FROM THIS LOCATION

NOTES:

1. BASE MAP PROVIDED BY WESTON SOLUTIONS OF MICHIGAN, INC.
2. LAND SURVEY ELEVATIONS WERE REFERENCED TO NAVD OF 1988 FEET MSL. THE HORIZONTAL LOCATIONS WERE REFERENCED TO THE MICHIGAN STATE PLANE COORDINATE SYSTEM NAD83, INTERNATIONAL FEET - SOUTH (2113) ZONE.
3. SMI - SOURCE MIGRATION INVESTIGATION
4. ALL RESULTS REPORTED IN MICROGRAMS PER LITER (ug/L).
5. "J" FLAGGED RESULTS ARE ESTIMATED.

FIGURE 3-11
LOWER UNIT, VOC DETECTIONS IN GROUNDWATER
SMI DATA EVALUATION REPORT
VELSICOL / PINE RIVER SITE
ST. LOUIS, MICHIGAN

CH2MHILL

File Path: E:\Velsicol\GIS_Data\Velsicol\MXDs\SMI\DRAFT_FINAL\03-11_Vel_LU_VOC_Results_May2005.mxd, Date: November 21, 2005, User: MPETERSH